

# MAX1631

	T41-BAD		T4O-GOOD		
PIN	OFF	ON	OFF	ON	SIGNAL
1	0	3.39			CSH3
2	0	3.39			CSL3
3	0	2.51			FB3
4	5.0	5.14			STEER
5	0	2.68			SECFB
6	4.57	4.68			SYNC
7	0	3.27	3.30	3.30	TIME/ON5
8	0	0			GND
9	2.50	2.50			REF
10	0	0			-SKIP
11	0	5.14			-RESET
12	0	2.51			FB5
13	0	5.15			CSL5
14	0	5.15			CSH5
15	2.5	2.50			SEQ
16	0	5.15			DH5
17	0	5.14			LX5
18	4.63	9.93			BST5
19	5.02	0			DL5
20	0				PGND
21	5.02	5.15			VL
22	15.57	16.11			V+
23	3.20	3.20			-SHDN
24	3.20	1.04			DL3
25	4.63	7.34			BST3
26	0	3.03			LX3
27	0	3.37			DH3
28	0	3.27	3.30	3.30	RUN/ON3