

MAX1845 U51

	T41-BAD		T4O-GOOD		
PIN	OFF	ON	OFF	ON	SIGNAL
1	0	0.55	1.84	1.81	OUT1
2					FB1
3					ILM1
4	15.56	16.0	16.0		V+
5					TON
6					-SKIP
7					PGOOD
8					OVP
9					UVP
10	0	0	2.0		REF
11	0	3.30	3.34	3.34	ON1
12	0	0	0	2.74	ON2
13					ILM2
14					FB2
15	0	0	0	1.51	OUT2
16					CS2
17					LX2
18					DH2
19					BST2
20					DL2
21	0	1.16	5.14		VDD
22	0	1.16	5.13	4.96	VCC
23					GND
24					DL1
25					BST1
26					DH1
27					LX1
28					CS1